


**16th US-Japan-NZ Workshop on the Improvement of
Structural Engineering and Resiliency
Nara, Japan, 27-29 June 2016**

2015 Gorkha (Nepal) Earthquake: An Overview






Professor Rajesh Dhakal, PhD, FIPENZ
Professor of Structural and Earthquake Engineering
Department of Civil and Natural Resources Engineering
University of Canterbury
Christchurch, New Zealand

Nepal, NZ, Japan and US West Coast: Similarity in Seismic Scenario





Seismicity of Nepal and Surrounding

FUNDAMENTAL FAULTING MECHANISMS




Layout of the Fault Planes




Gorkha Earthquake: Basic Facts

- When?: 25 April 2015 Saturday 11:56 am Local time
- Magnitude: 7.6-7.9
- Depth: 10-15 Km
- Epicentre: Near Barpak Village, Gorkha (78km North West from Kathmandu, similar distance to the East from Pokhara)
- Followed by hundreds of aftershocks, the most damaging one was of Magnitude 6.8 on 12 May
- Effects:
 - 8800+ deaths, about 20,000 injured
 - About 500,000 houses/buildings damaged
 - Loss: approximately 6.6 billion dollars (~33% of GDP)


Eastward Rupture Propagation



Seismic Intensity Contours



Trend of Aftershocks



Apr 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 May 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 Jun 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Most Non-Engineered Houses Collapsed






Hilly settlements were hit harder: Ridge effect






Severe Impact on Educational Facilities



Severe Damage to Heritage Sites



Religious Precincts also Suffered



Damage to Walls: A Common Sight in Tall Buildings



Buildings were affected also by poor performance of soil and foundation



Lokanthali (Bhaktapur)



Itahari (400 km east of Kathmandu)



For Many, the Cause was Obvious

- No anti-seismic features in design/construction
- Fundamental technical faults in buildings
 - Slender columns
 - Insufficient reinforcement
 - Inadequate splice/anchorage
 - Inadequate confinement
 - Poor detailing
 - Unnecessarily thick plaster
- Poor material quality
- Amplification of ground shaking due to local geological features
- Foundation depth/type not adequate for the local soil condition



Technically, Nepal was in a state of

Reasonable Knowledge, Limited Preparedness, Mixed practice



New Buildings: Some Good Examples



Buildings under construction: Bad Examples



Gongabu



Incorrect strength hierarchy



Engineering Advice: At least being Sought for Commercial Buildings

Reg. No. 10256/046

Date: 3rd May, 2015

To,
General Manager,
EBL House,
Lazimpat, Kathmandu.

Dear Sir,

As per your request I performed the detail visual inspection of Everest Bank Ltd House's at Lazimpat Corporate & Banking building structure from outside perimeter & interior closely and I could not find any structural problem and whatever cracks seen found to be surfacial only. This was confirmed after breaking open the plaster layer and found the concrete part intact. Hence, I like to state hereby that **the building structure is safe for Operation.**

Sincerely Yours,

Building Tagging

RESTRICTED USE

Caution: This structure has been inspected and found to be damaged as described below:
*Cracking of brick walls observed few
Minor hair pin crack observed in
shear wall. Detail structural
evaluation recommended*

Date 2072/02/01
Time 11:55 AM

Entry, occupancy, and lawful use are restricted as indicated below:

Do not enter the following areas: *Restricted use
in the periphery of cracked walls*

Brief entry allowed for access to contents: _____

Other restrictions: _____

Facility name and address:
*Silvercity luxury Apartment,
Kali Kothari, Kathmandu.*

This facility was inspected under emergency conditions for: Eq
(Jurisdiction)

Inspector ID / Agency:
*Department of Urban Development
and Building Construction
Rapid Assessment Team-6 (RAT-6)
Nepal Land and Housing Forum
Developers Association
Society of Nepali Architects (SONA)
Prayag*

Do Not Remove, Alter, or Cover this Placard until Authorized by Governing Authority

Remarks: *Jointly Inspected with New-Zealand Engineering Team.*

UNSAFE

DO NOT ENTER OR OCCUPY

Warning: This Structure has been seriously damaged and is unsafe. Do Not enter. Entry may result in death or injury.

Date: 2072-1-20
Time: 11:30 am

Comments:
*Sever cracks in
slab & walls.*

Facility Name and Address:
Supreme Court.

Do Not Remove This Placard until Authorized by Governing Authority.

*Pratiksha Tulakh
(CDF)*

In general, the practice was of international standard

Shoring/Protection of Damaged Structures



This is how buildings are shored in NZ



Problems/Challenges Immediately after the Earthquakes

- Misinterpretation of colour tags
- Crack-phobia among public
- Shortage of engineers with earthquake engineering expertise
- Professionals speaking outside area of competence
- Scarcity of demolition skill and equipment
- Debris clearance
- Confused authorities/people

My Past Involvement (May 15-Jan 16)



Assessing Hospitals and Advising Medics



Building Inspection and Counselling



Advising Government Officials



Educating Good Practice to Masons



Raising Public Awareness on Seismic Risk



Educating Junior/Fresh Engineers & Students

Shortage of engineers with knowledge/expertise in earthquake engineering



Interaction with Senior Engineers

Professionals speaking/advising outside their area of competence was common



My ongoing/future involvements in Nepal's long-term recovery to seismic resiliency

- Development of earthquake engineering qualifications in Universities
- National Building Code Revision
- National Earthquake Engineering Centre of Excellence
- Facilitating the transfer of low-cost and safe construction techniques developed overseas (Earthbag Technology)

Earthbag Technology



Where to from hereon?

Big earthquakes cause unbearable pain, but also provide a golden opportunity to develop a more resilient community that is better equipped to combat similar disasters in future

- Develop/improve the building codes
- Establish robust construction quality control mechanisms
- Establish mechanisms to ensure the codes/rules are strictly followed
- Urban development strategy based on a sound land use planning
- Develop comprehensive soil mapping and reconstruct to suit the local soil condition
- Start state-of-the-art earthquake engineering education and training for capacity enhancement




Historic Major Earthquakes in Nepal

Timeline: Nepal earthquakes


@ajlabs

Nepal has been struck by the biggest earthquake in over 80 years. The region that has been hit hardest is the very populous Kathmandu valley.




Ground Motion Record

Kanti Path, Kathmandu, Nepal USGS Sta KATNP
Record of Sat Apr 25, 2015 06:11:46.6 GMT
Filtering: Highpass at .02 Hz (50 secs)
USGS Strong Motion Processing



Response Spectra



The shakings were larger than the design level for all structures except very stiff ($T < 0.3s$) structures; i.e. 1-2 storey stiff load bearing houses, Rana era palaces with thick stiff walls

NS shaking: gentle to stiff structures, but very harsh on tall/flexible ($T > 3s$) structures

EW shaking: High demand on structures around 0.5s period as well.

But, the shaking intensity was still less than what is normally expected of a 7.9 magnitude earthquake at 75km away.

Kathmandu basin's clay deposits appear to have suppressed low frequency (characterised by high acceleration but small displacement) motions and transferred with amplification the low frequency (large displacement but small acceleration) motions.

This logic is in line with people's recollection of the shaking and the only record available.

