

**SEAW/ATC-60, Volume 2**  
**Errata for Preprint Edition, First Printing**

<b>Appendix/Section/Figure</b>	<b>Page</b>	<b>Correction</b>
Cover	Cover	Second line of title should read: “Volume 2 – Example problems”
Title page	i	Second line of title should read: “Volume 2 – Example Problems”
Section C1.1.2.2	C1-8	Section C1.1.2.2, first line: Replace “10” with “9”.
C3	All of C3	For Appendix C3: Example Problem 3-MWFRS and C&C: Tilt-Up Building Subject to Wind Speed-Up Effects, refer to the new Appendix C3 provided with this errata.