

FEMA 307

EVALUATION OF EARTHQUAKE DAMAGED CONCRETE AND MASONRY WALL BUILDINGS

Technical Resources

Prepared by:



The Applied Technology Council

555 Twin Dolphin Drive, Suite 550
Redwood City, California 94065

Prepared for:

The Partnership for Response and Recovery

Washington, D.C.

Funded by:

Federal Emergency Management Agency

1998

Applied Technology Council

The Applied Technology Council (ATC) is a nonprofit, tax-exempt corporation established in 1971 through the efforts of the Structural Engineers Association of California. ATC is guided by a Board of Directors consisting of representatives appointed by the American Society of Civil Engineers, the Structural Engineers Association of California, the Western States Council of Structural Engineers Associations, and four at-large representatives concerned with the practice of structural engineering. Each director serves a three-year term.

The purpose of ATC is to assist the design practitioner in structural engineering (and related design specialty fields such as soils, wind, and earthquake) in the task of keeping abreast of and effectively using technological developments. ATC also identifies and encourages needed research and develops consensus opinions on structural engineering issues in a nonproprietary format. ATC thereby fulfills a unique role in funded information transfer.

Project management and administration are carried out by a full-time Executive Director and support staff. Project work is conducted by a wide range of highly qualified consulting professionals, thus incorporating the experience of many individuals from academia, research, and professional practice who would not be available from any single organization. Funding for ATC projects is obtained from government agencies and from the private sector in the form of tax-deductible contributions.

1998-1999 Board of Directors

Charles H. Thornton, President
Edwin T. Dean, Vice President
Andrew T. Merovich, Secretary/
Treasurer
C. Mark Saunders, Past President
James R. Cagley
Arthur N. L. Chiu
Robert G. Dean

Edwin H. Johnson
Kenneth A. Luttrell
Newland J. Malmquist
Stephen H. Pelham
Richard J. Phillips
Charles W. Roeder
Jonathan G. Shipp

Notice

This report was prepared under Contract EMW-95-C-4685 between the Federal Emergency Management Agency and the Partnership for Response and Recovery.

Any opinions, findings, conclusions, or recommendations expressed in this publication do not necessarily reflect the views of the Applied Technology Council (ATC), the Partnership for Response and Recovery (PaRR), or the Federal Emergency Management Agency (FEMA). Additionally, neither ATC, PaRR, FEMA, nor any of their employees makes any warranty, expressed or implied, nor assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, product, or process included in this publication. Users of information from this publication assume all liability arising from such use.

For further information concerning this document or the activities of the ATC, contact the Executive Director, Applied Technology Council, 555 Twin Dolphin Drive, Suite 550, Redwood City, California 94065; phone 650-595-1542; fax 650-593-2320; e-mail atc@atcouncil.org.

Preface

Following the two damaging California earthquakes in 1989 (Loma Prieta) and 1994 (Northridge), many concrete wall and masonry wall buildings were repaired using federal disaster assistance funding. The repairs were based on inconsistent criteria, giving rise to controversy regarding criteria for the repair of cracked concrete and masonry wall buildings. To help resolve this controversy, the Federal Emergency Management Agency (FEMA) initiated a project on evaluation and repair of earthquake damaged concrete and masonry wall buildings in 1996. The project was conducted through the Partnership for Response and Recovery (PaRR), a joint venture of Dewberry & Davis of Fairfax, Virginia, and Woodward-Clyde Federal Services of Gaithersburg, Maryland. The Applied Technology Council (ATC), under subcontract to PaRR, was responsible for developing technical criteria and procedures (the ATC-43 project).

The ATC-43 project addresses the investigation and evaluation of earthquake damage and discusses policy issues related to the repair and upgrade of earthquake-damaged buildings. The project deals with buildings whose primary lateral-force-resisting systems consist of concrete or masonry bearing walls with flexible or rigid diaphragms, or whose vertical-load-bearing systems consist of concrete or steel frames with concrete or masonry infill panels. The intended audience is design engineers, building owners, building regulatory officials, and government agencies.

The project results are reported in three documents. The FEMA 306 report, *Evaluation of Earthquake Damaged Concrete and Masonry Wall Buildings, Basic Procedures Manual*, provides guidance on evaluating damage and analyzing future performance. Included in the document are component damage classification guides, and test and inspection guides. FEMA 307, *Evaluation of Earthquake Damaged Concrete and Masonry Wall Buildings, Technical Resources*, contains supplemental information including results from a theoretical analysis of the effects of prior damage on single-degree-of-freedom mathematical models, additional background information on the component guides, and an example of the application of the basic procedures. FEMA 308, *The Repair of Earthquake Damaged Concrete and Masonry Wall Buildings*, discusses the policy issues pertaining to the repair of earthquake damaged buildings and illustrates how the procedures developed for the project can be used to provide a technically sound basis for policy decisions. It

also provides guidance for the repair of damaged components.

The project also involved a workshop to provide an opportunity for the user community to review and comment on the proposed evaluation and repair criteria. The workshop, open to the profession at large, was held in Los Angeles on June 13, 1997 and was attended by 75 participants.

The project was conducted under the direction of ATC Senior Consultant Craig Comartin, who served as Co-Principal Investigator and Project Director. Technical and management direction were provided by a Technical Management Committee consisting of Christopher Rojahn (Chair), Craig Comartin (Co-Chair), Daniel Abrams, Mark Doroudian, James Hill, Jack Moehle, Andrew Merovich (ATC Board Representative), and Tim McCormick. The Technical Management Committee created two Issue Working Groups to pursue directed research to document the state of the knowledge in selected key areas: (1) an Analysis Working Group, consisting of Mark Aschheim (Group Leader) and Mete Sozen (Senior Consultant) and (2) a Materials Working Group, consisting of Joe Maffei (Group Leader and Reinforced Concrete Consultant), Greg Kingsley (Reinforced Masonry Consultant), Bret Lizundia (Unreinforced Masonry Consultant), John Mander (Infilled Frame Consultant), Brian Kehoe and other consultants from Wiss, Janney, Elstner and Associates (Tests, Investigations, and Repairs Consultant). A Project Review Panel provided technical overview and guidance. The Panel members were Gregg Borchelt, Gene Corley, Edwin Huston, Richard Klingner, Vilas Mujumdar, Hassan Sassi, Carl Schulze, Daniel Shapiro, James Wight, and Eugene Zeller. Nancy Sauer and Peter Mork provided technical editing and report production services, respectively. Affiliations are provided in the list of project participants.

The Applied Technology Council and the Partnership for Response and Recovery gratefully acknowledge the cooperation and insight provided by the FEMA Technical Monitor, Robert D. Hanson.

Tim McCormick
PaRR Task Manager

Christopher Rojahn
ATC-43 Principal Investigator
ATC Executive Director

Table of Contents

Preface	iii
List of Figures	ix
List of Tables	xiii
Prologue	xv
1. Introduction	1
1.1 Purpose And Scope	1
1.2 Materials Working Group	1
1.2.1 Tests and Investigations	1
1.2.2 Component Behavior and Modeling	1
1.2.3 Repair Techniques	2
1.3 Analysis Working Group	3
1.4 References	4
2. Reinforced Concrete Components	7
2.1 Commentary and Discussion	7
2.1.1 Development of Component Guides and λ -Factors	7
2.2 Typical Force-Displacement Hysteretic Behavior	10
2.3 Tabular Bibliography	28
2.4 Symbols for Reinforced Concrete	33
2.5 References for Reinforced Concrete	35
3. Reinforced Masonry	39
3.1 Commentary and Discussion	39
3.1.1 Typical Hysteretic Behavior	39
3.1.2 Cracking and Damage Severity	39
3.1.3 Interpretation of Tests	46
3.2 Tabular Bibliography for Reinforced Masonry	46
3.3 Symbols for Reinforced Masonry	53
3.4 References for Reinforced Masonry	54
4. Unreinforced Masonry	59
4.1 Commentary and Discussion	59
4.1.1 Hysteretic Behavior of URM Walls Subjected to In-Plane Demands	59
4.1.2 Comments on FEMA 273 Component Force/Displacement Relationships	72
4.1.3 Development of λ -factors	75
4.2 Tabular Bibliography for Unreinforced Masonry	77
4.3 Symbols for Unreinforced Masonry	80

4.4	References for Unreinforced Masonry	81
5.	Infilled Frames	85
5.1	Commentary And Discussion	85
5.1.1	Development of λ -Factors for Component Guides	85
5.1.2	Development of Stiffness Deterioration— λ_K	85
5.1.3	The Determination of λ_Q for Strength Deterioration	86
5.1.4	Development of λ_D —Reduction in Displacement Capability	87
5.2	Tabular Bibliography for Infilled Frames	89
5.3	References for Infilled Frames	91
6.	Analytical Studies	95
6.1	Overview	95
6.2	Summary of Previous Findings	95
6.2.1	Hysteresis Models	95
6.2.2	Effect of Ground Motion Duration	98
6.2.3	Residual Displacement	98
6.2.4	Repeated Loading	98
6.3	Dynamic Analysis Framework	99
6.3.1	Overview	99
6.3.2	Dynamic Analysis Approach	99
6.3.3	Ground Motions	100
6.3.4	Force/Displacement Models	120
6.3.5	Undamaged Oscillator Parameters	122
6.3.6	Damaged Oscillator Parameters	123
6.3.7	Summary of Dynamic Analysis Parameters	125
6.3.8	Implementation of Analyses	126
6.4	Results Of Dynamic Analyses	126
6.4.1	Overview and Nomenclature	126
6.4.2	Response of Bilinear Models	127
6.4.3	Response of Takeda Models	127
6.4.4	Response Statistics	151
6.5	Nonlinear Static Procedures	155
6.5.1	Introduction	155
6.5.2	Description of Nonlinear Static Procedures	156
6.5.3	Comments on Procedures	159
6.5.4	Application of Procedures to Undamaged and Damaged Oscillators	160
6.6	Comparison of NSP and Dynamic Analysis Results	160
6.6.1	Introduction	160
6.6.2	Displacement Estimation	160
6.6.3	Displacement Ratio Estimation	161
6.7	Conclusions and Implications	177
6.8	References	178

7.	Example Application	181
7.1	Introduction	181
7.1.1	Objectives	181
7.1.2	Organization	181
7.2	Investigation	183
7.2.1	Building Description	183
7.2.2	Postearthquake Damage Observations	183
7.2.3	Preliminary Classification (by Observation) of Component Types, Behavior Modes, and Damage Severity	189
7.2.4	Final Classification (by Analysis) of Component Type, Behavior Mode and Damage Severity	190
7.2.5	Other Damage Observations	195
7.2.6	Summary of Component Classifications	195
7.3	Evaluation by the Direct Method	199
7.3.1	Structural Restoration Measures	199
7.3.2	Nonstructural Restoration Measures	201
7.3.3	Restoration Summary and Cost	201
7.4	Evaluation by Performance Analysis	201
7.4.1	Performance Objectives	202
7.4.2	Nonlinear Static Analysis	203
7.4.3	Force-Displacement Capacity (Pushover Analysis) Results	206
7.4.4	Estimation of Displacement, d_e , Caused by Damaging Earthquake	209
7.4.5	Displacement Demand	210
7.4.6	Analysis of Restored Structure	212
7.4.7	Performance Restoration Measures	214
7.5	Discussion of Results	214
7.5.1	Discussion of Building Performance	214
7.5.2	Discussion of Methodology and Repair Costs	215
7.6	References	215
Appendix A. Component Damage Records for Building Evaluated in Example Application		217
ATC-43 Project Participants		237
Applied Technology Council Projects And Report Information		241

List of Figures

Figure 1-1	Component Force-Deformation Relationships	2
Figure 1-2	Generalized Undamaged and Damaged Component Curves	3
Figure 1-3	Effect of Damage on Building Response	4
Figure 1-4	Global Load-Displacement Relationships	5
Figure 2-1	Diagram of process used to develop component guides and component modification factors.	8
Figure 4-1	Bed-joint sliding force/displacement relationship	73
Figure 4-2	Relationship Between Toe Crushing and Bed-Joint Sliding	74
Figure 4-3	Developing the initial portion of the damaged force/displacement relationship	76
Figure 5-1	Energy-based damage analysis of strength reduction to define λ_Q	88
Figure 6-1	Effect of Hysteretic Properties on Response to 1940 NS El Centro Record (from Nakamura, 1988)	97
Figure 6-2	Characteristics of the WN87MWLN.090 (Mount Wilson) Ground Motion	102
Figure 6-3	Characteristics of the BB92CIVC.360 (Big Bear) Ground Motion	103
Figure 6-4	Characteristics of the SP88GUKA.360 (Spitak) Ground Motion	104
Figure 6-5	Characteristics of the LP89CORR.090 (Corralitos) Ground Motion	105
Figure 6-6	Characteristics of the NR94CENT.360 (Century City) Ground Motion	106
Figure 6-7	Characteristics of the IV79ARY7.140 (Imperial Valley Array) Ground Motion	107
Figure 6-8	Characteristics of the CH85LLEO.010 (Llolleo) Ground Motion	108
Figure 6-9	Characteristics of the CH85VALP.070 (Valparaiso University) Ground Motion	109
Figure 6-10	Characteristics of the IV40ELCN.180 (El Centro) Ground Motion	110
Figure 6-11	Characteristics of the TB78TABS.344 (Tabas) Ground Motion	111
Figure 6-12	Characteristics of the LN92JOSH.360 (Joshua Tree) Ground Motion	112
Figure 6-13	Characteristics of the MX85SCT1.270 (Mexico City) Ground Motion	113
Figure 6-14	Characteristics of the LN92LUCN.250 (Lucerne) Ground Motion	114
Figure 6-15	Characteristics of the IV79BRWY.315 (Brawley Airport) Ground Motion	115
Figure 6-16	Characteristics of the LP89SARA.360 (Saratoga) Ground Motion	116
Figure 6-17	Characteristics of the NR94NWHL.360 (Newhall) Ground Motion	117
Figure 6-18	Characteristics of the NR94SYLH.090 (Sylmar Hospital) Ground Motion	118
Figure 6-19	Characteristics of the KO95TTRI.360 (Takatori) Ground Motion	119
Figure 6-20	Force-Displacement Hysteretic Models	120
Figure 6-21	Degrading Models Used in the Analyses	121
Figure 6-22	Bilinear Model Used to Determine Strengths of Degrading Models	122
Figure 6-23	Specification of the Pinching Point for the Takeda Pinching Model	122
Figure 6-24	Specification of the Uncracked Stiffness, Cracking Strength, and Unloading Stiffness for the Takeda Models	123
Figure 6-25	Construction of Initial Force-Displacement Response for Prior Ductility Demand > 0 and Reduced Strength Ratio = 1	123
Figure 6-26	Construction of Initial Force-Displacement Response for PDD > 0 and RSR < 1 for Takeda5 and Takeda10 Models	124

Figure 6-27	Strength Degradation for Takeda Pinching Model	125
Figure 6-28	Construction of Initial Force-Displacement Response for $PDD > 0$ and $RSR < 1$ for Takeda Pinching Model	126
Figure 6-29	Response of Bilinear Oscillators to Short Duration Records ($DDD = 8$)	128
Figure 6-30	Response of Bilinear Oscillators to Long Duration Records ($DDD = 8$)	129
Figure 6-31	Response of Bilinear Oscillators to Forward Directive Records ($DDD = 8$)	130
Figure 6-32	Displacement Response of Takeda Models Compared with Elastic Response and Bilinear Response, for Short-Duration Records ($DDD = 8$ and $RSR = 1$)	131
Figure 6-33	Displacement Response of Takeda Models Compared with Elastic Response and Bilinear Response for Long-Duration Records ($DDD = 8$ and $RSR = 1$)	132
Figure 6-34	Displacement Response of Takeda Models Compared with Elastic Response and Bilinear Response for Forward Directive Records ($DDD = 8$ and $RSR = 1$)	133
Figure 6-35	Effect of Cracking Without and With Strength Reduction on Displacement Response of Takeda5 Models, for Short-Duration Records ($DDD = 8$ and $PDD = 1$)	135
Figure 6-36	Effect of Cracking Without and With Strength Reduction on Displacement Response of Takeda5 Models, for Long-Duration Records ($DDD = 8$ and $PDD = 1$)	136
Figure 6-37	Effect of Cracking Without and With Strength Reduction on Displacement Response of Takeda5 Models, for Forward Directive Records ($DDD = 8$ and $PDD = 1$)	137
Figure 6-38	Effect of Large Prior Ductility Demand Without and With Strength Reduction on Displacement Response of Takeda5 Models, for Short Duration Records ($DDD = 8$ and $PDD = 8$)	138
Figure 6-39	Effect of Large Prior Ductility Demand Without and With Strength Reduction on Displacement Response of Takeda5 Models, for Long Duration Records ($DDD = 8$ and $PDD = 8$)	139
Figure 6-40	Effect of Large Prior Ductility Demand Without and With Strength Reduction on Displacement Response of Takeda5 Models, for Forward Directive Records ($DDD = 8$ and $PDD = 8$)	140
Figure 6-41	Effect of Damage on Response to El Centro (IV40ELCN.180) for Takeda5, $T = 0.2$ sec ($DDD = 8$)	141
Figure 6-42	Effect of Damage on Response to El Centro (IV40ELCN.180) for Takeda5, $T = 0.5$ sec ($DDD = 8$)	142
Figure 6-43	Effect of Damage on Response to El Centro (IV40ELCN.180) for Takeda5, $T = 1.0$ sec ($DDD = 8$)	143
Figure 6-44	Effect of Damage on Response to El Centro (IV40ELCN.180) for Takeda5, $T = 1.5$ sec ($DDD = 8$)	144
Figure 6-45	Effect of Damage on Response to El Centro (IV40ELCN.180) for Takeda5, $T = 2.0$ sec ($DDD = 8$)	145
Figure 6-46	Effect of Large Prior Ductility Demand Without and With Strength Reduction on Displacement Response of TakPinch Models, for Short Duration Records ($DDD = 8$ and $PDD = 8$)	146
Figure 6-47	Effect of Large Prior Ductility Demand Without and With Strength Reduction on Displacement Response of TakPinch Models, for Long Duration Records ($DDD = 8$ and $PDD = 8$)	147
Figure 6-48	Effect of Large Prior Ductility Demand Without and With Strength Reduction on Displacement Response of TakPinch, for Forward Directive Records ($DDD = 8$ and $PDD = 8$)	148
Figure 6-49	Effect of Damage on Response of TakPinch Model to El Centro (IV40ELCN.180) for	

	T=1.0 sec and RSR= 1 (DDD= 8)	149
Figure 6-50	Effect of Damage on Response of TakPinch Model to El Centro (IV40ELCN.180) for T=1.0 sec and RSR = 0.6 (DDD= 8)	150
Figure 6-51	Effect of Cracking on Displacement Response of Takeda10 Model for Short Duration Records (DDD= 8 and PDD=1)	151
Figure 6-52	Effect of Cracking on Displacement Response of Takeda10 Model for Long-Duration Records (DDD= 8 and PDD=1)	152
Figure 6-53	Effect of Cracking on Displacement Response of Takeda10 Model for Forward Directive Records (DDD= 8 and PDD=1)	152
Figure 6-54	Effect of Damage on Response of Takeda10 Model to El Centro (IV40ELCN.180) for T=1.0 sec and RSR= 1 (DDD= 8)	153
Figure 6-55	Mean and Standard Deviation Values of d'_d/d_d for Takeda5 Model.	154
Figure 6-56	Mean and Standard Deviation Values of d'_d/d_d for TakPinch Model.	155
Figure 6-57	Percent of Takeda10 Oscillators that Collapsed	156
Figure 6-58	Construction of Effective Stiffness for use with the Displacement Coefficient Method	157
Figure 6-59	Initial Effective Stiffness and Capacity Curves Used in the Secant and Capacity Spectrum Methods	158
Figure 6-60	Schematic Depiction of Secant Method Displacement Estimation	158
Figure 6-61	Schematic Depiction of Successive Iterations to Estimate Displacement Response Using the Secant Method for Single-Degree-of-Freedom Oscillators	159
Figure 6-62	Schematic Depiction of Successive Iterations to Estimate Displacement Response Using the Capacity Spectrum Method	159
Figure 6-63	Values of $d_{d,NSP}/d_d$ for the Takeda5 Model	162
Figure 6-64	Mean values of $d_{d,NSP}/d_d$ for all ground motions for each NSP method, for short and long-period Takeda5 Models. See text in Section 6.6.3.	163
Figure 6-65	Coefficient Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Short-Duration Records	163
Figure 6-66	Coefficient Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Long-Duration Records	164
Figure 6-67	Coefficient Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Forward Directive Records	164
Figure 6-68	Secant Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Short-Duration Records	165
Figure 6-69	Secant Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Long-Duration Records	165
Figure 6-70	Secant Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Forward Directive Records	166
Figure 6-71	Capacity Spectrum Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Short-Duration Records	166
Figure 6-72	Capacity Spectrum Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Long-Duration Records	167
Figure 6-73	Capacity Spectrum Method Estimates of Ratio of Damaged and Undamaged Oscillator Displacement Normalized by Computed Ratio, for Forward Directive Records	167
Figure 6-74	Coefficient Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0 Takeda5 Oscillators having DDD= 8 and PDD= 1	168
Figure 6-75	Coefficient Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0	

	Takeda5 Oscillators having DDD= 8 and PDD= 1	169
Figure 6-76	Coefficient Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0 Takeda5 Oscillators having DDD= 8 and PDD= 1	170
Figure 6-77	Secant Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0 Takeda5 Oscillators having DDD= 8 and PDD= 1	171
Figure 6-78	Secant Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0 Takeda5 Oscillators having DDD= 8 and PDD= 1	172
Figure 6-79	Secant Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0 Takeda5 Oscillators having DDD= 8 and PDD= 1	173
Figure 6-80	Capacity Spectrum Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0 Takeda5 Oscillators having DDD= 8 and PDD= 1	174
Figure 6-81	Capacity Spectrum Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0 Takeda5 Oscillators having DDD= 8 and PDD= 1	175
Figure 6-82	Capacity Spectrum Method Estimates of Displacement Ratio of RSR=0.6 and RSR=1.0 Takeda5 Oscillators having DDD= 8 and PDD= 1	176
Figure 7-1	Flowchart for Example	182
Figure 7-2	Floor Plans	184
Figure 7-3	Building Cross-section	185
Figure 7-4	Example Solid Wall Detail	185
Figure 7-5	Example Coupled Wall Detail	186
Figure 7-6	Solid Wall Example	187
Figure 7-7	Coupled Wall Example	188
Figure 7-8	Detail of Coupling Beam Replacement	202
Figure 7-9	Response Spectra for Selected Performance Levels	203
Figure 7-10	Mathematical Model of Coupled Shear Wall	204
Figure 7-11	Mathematical Model of Full Building	205
Figure 7-12	Component Force-Displacement Curves for Coupling Beams	207
Figure 7-13	Comparison of Pre-event and Post-event Pushover Curves	208
Figure 7-14	Response Spectra from Damaging Earthquake	209
Figure 7-15	Comparison of Pre-event and Repaired Pushover Curves	213

List of Tables

Table 2-1	Ranges of Reinforced Concrete Component Displacement Ductility, μ_{Δ} , Associated with Damage Severity Levels and λ Factors	9
Table 2-2	Key References on Reinforced Concrete Wall Behavior.	29
Table 3-1	Damage Patterns and Hysteretic Response for Reinforced Masonry Components	40
Table 3-2	Ranges of Reinforced Masonry Component Displacement Ductility, μ_{Δ} , Associated with Damage Severity Levels and λ Factors	47
Table 3-3	Annotated Bibliography for Reinforced Masonry	48
Table 4-1	Summary of Significant Experimental Research or Research Summaries	78
Table 5-1	Tabular Bibliography for Infilled Frames	89
Table 6-1	Recorded Ground Motions Used in the Analyses	101
Table 7-1	Capacity of Potential Behavior Modes for Typical Solid Wall	191
Table 7-2	Capacity of Potential Behavior Modes for Typical Coupling Beam	193
Table 7-3	Shear Capacities for Potential Behavior Modes of Wall Pier (RC1) Components in Coupled Wall	194
Table 7-4	Summary of Component Type, Behavior Mode, and Damage Severity for Wall Components (North-South Direction)	200
Table 7-5	Summary of Component Type, Behavior Mode, and Damage Severity for Wall Components (East-West Direction)	201
Table 7-6	Restoration Cost Estimate by the Direct Method	202
Table 7-7	Performance Indices for Pre-event and Post-event Structures	212
Table 7-8	Restoration Cost Estimate by the Relative Performance Method	214

Prologue

This document is one of three to result from the ATC-43 project funded by the Federal Emergency Management Agency (FEMA). The goal of the project is to develop technically sound procedures to evaluate the effects of earthquake damage on buildings with primary lateral-force-resisting systems consisting of concrete or masonry bearing walls or infilled frames. The procedures are based on the knowledge derived from research and experience in engineering practice regarding the performance of these types of buildings and their components. The procedures require thoughtful examination and review prior to implementation. The ATC-43 project team strongly urges individual users to read all of the documents carefully to form an overall understanding of the damage evaluation procedures and repair techniques.

Before this project, formalized procedures for the investigation and evaluation of earthquake-damaged buildings were limited to those intended for immediate use in the field to identify potentially hazardous conditions. ATC-20, *Procedures for Postearthquake Safety Evaluation of Buildings*, and its addendum, ATC-20-2 (ATC, 1989 and 1995) are the definitive documents for this purpose. Both have proven to be extremely useful in practical applications. ATC-20 recognizes and states that in many cases, detailed structural engineering evaluations are required to investigate the implications of earthquake damage and the need for repairs. This project provides a framework and guidance for those engineering evaluations.

What have we learned?

The project team for ATC-43 began its work with a thorough review of available analysis techniques, field observations, test data, and emerging evaluation and design methodologies. The first objective was to understand the effects of damage on future building performance. The main points are summarized below.

- **Component behavior controls global performance.**

Recently developed guidelines for structural engineering seismic analysis and design techniques focus on building displacement, rather than forces as the primary parameter for the characterization of

seismic performance. This approach models the building as an assembly of its individual components. Force-deformation properties (e.g., elastic stiffness, yield point, ductility) control the behavior of wall panels, beams, columns, and other components. The component behavior, in turn, governs the overall displacement of the building and its seismic performance. Thus, the evaluation of the effects of damage on building performance must concentrate on how component properties change as a result of damage.

- **Indicators of damage (e.g., cracking, spalling) are meaningful only in light of the mode of component behavior.**

Damage affects the behavior of individual components differently. Some exhibit ductile modes of post-elastic behavior, maintaining strength even with large displacements. Others are brittle and lose strength abruptly after small inelastic displacements. The post-elastic behavior of a structural component is a function of material properties, geometric proportions, details of construction, and the combination of demand actions (axial, flexural, shearing, torsional) imposed upon it. As earthquake shaking imposes these actions on components, the components tend to exhibit predominant modes of behavior as damage occurs. For example, if earthquake shaking and its associated inertial forces and frame distortions cause a reinforced concrete wall panel to rotate at each end, statics defines the relationship between the associated bending moments and shear force. The behavior of the panel depends on its strength in flexure relative to that in shear. Cracks and other signs of damage must be interpreted in the context of the mode of component behavior. A one-eighth-inch crack in a wall panel on the verge of brittle shear failure is a very serious condition. The same size crack in a flexurally-controlled panel may be insignificant with regard to future seismic performance. This is, perhaps, the most important finding of the ATC-43 project: the significance of cracks and other signs of damage, with respect to the future performance of a building, depends on the mode of behavior of the components in which the damage is observed.

- **Damage may reveal component behavior that differs from that predicted by evaluation and design methodologies.**

When designing a building or evaluating an undamaged building, engineers rely on theory and their own experience to visualize how earthquakes will affect the structure. The same is true when they evaluate the effects of actual damage after an earthquake, with one important difference. If engineers carefully observe the nature and extent of the signs of the damage, they can greatly enhance their insight into the way the building actually responded to earthquake shaking. Sometimes the actual behavior differs from that predicted using design equations or procedures. This is not really surprising, since design procedures must account conservatively for a wide range of uncertainty in material properties, behavior parameters, and ground shaking characteristics. Ironically, actual damage during an earthquake has the potential for improving the engineer's knowledge of the behavior of the building. When considering the effects of damage on future performance, this knowledge is important.

- **Damage may not significantly affect displacement demand in future larger earthquakes.**

One of the findings of the ATC-43 project is that prior earthquake damage does not affect maximum displacement response in future, larger earthquakes in many instances. At first, this may seem illogical. Observing a building with cracks in its walls after an earthquake and visualizing its future performance in an even larger event, it is natural to assume that it is worse off than if the damage had not occurred. It seems likely that the maximum displacement in the future, larger earthquake would be greater than if it had not been damaged. Extensive nonlinear time-history analyses performed for the project indicated otherwise for many structures. This was particularly true in cases in which significant strength degradation did not occur during the prior, smaller earthquake. Careful examination of the results revealed that maximum displacements in time histories of relatively large earthquakes tended to occur after the loss of stiffness and strength would have taken place even in an undamaged structure. In other words, the damage that occurs in a prior,

smaller event would have occurred early in the subsequent, larger event anyway.

What does it mean?

The ATC-43 project team has formulated performance-based procedures for evaluating the effects of damage. These can be used to quantify losses and to develop repair strategies. The application of these procedures has broad implications.

- **Performance-based damage evaluation uses the actual behavior of a building, as evidenced by the observed damage, to identify specific deficiencies.**

The procedures focus on the connection between damage and component behavior and the implications for estimating actual behavior in future earthquakes. This approach has several important benefits. First, it provides a meaningful engineering basis for measuring the effects of damage. It also identifies performance characteristics of the building in its pre-event and damaged states. The observed damage itself is used to calibrate the analysis and to improve the building model. For buildings found to have unacceptable damage, the procedures identify specific deficiencies at a component level, thereby facilitating the development of restoration or upgrade repairs.

- **Performance-based damage evaluation provides an opportunity for better allocation of resources.**

The procedures themselves are technical engineering tools. They do not establish policy or prescribe rules for the investigation and repair of damage. They may enable improvements in both private and public policy, however. In past earthquakes, decisions on what to do about damaged buildings have been hampered by a lack of technical procedures to evaluate the effects of damage and repairs. It has also been difficult to investigate the risks associated with various repair alternatives. The framework provided by performance-based damage evaluation procedures can help to remove some of these roadblocks. In the long run, the procedures may tend to reduce the prevailing focus on the loss caused by damage from its pre-event conditions and to increase the focus on what the damage reveals about future building performance. It makes little

sense to implement unnecessary repairs to buildings that would perform relatively well even in a damaged condition. Nor is it wise to neglect buildings in which the component behavior reveals serious hazards regardless of the extent of damage.

- **Engineering judgment and experience are essential to the successful application of the procedures.**

ATC-20 and its addendum, ATC-20-2, were developed to be used by individuals who might be somewhat less knowledgeable about earthquake building performance than practicing structural engineers. In contrast, the detailed investigation of damage using the performance-based procedures of this document and the companion FEMA 306 report (ATC, 1998a) and FEMA 308 report (ATC, 1998b) must be implemented by an experienced engineer. Although the documents include information in concise formats to facilitate field operations, they must not be interpreted as a “match the pictures” exercise for unqualified observers. Use of these guideline materials requires a thorough understanding of the underlying theory and empirical justifications contained in the documents. Similarly, the use of the simplified direct method to estimate losses has limitations. The decision to use this method and the interpretation of the results must be made by an experienced engineer.

- **The new procedures are different from past damage evaluation techniques and will continue to evolve in the future.**

The technical basis of the evaluation procedures is essentially that of the emerging performance-based

seismic and structural design procedures. These will take some time to be assimilated in the engineering community. The same is true for building officials. Seminars, workshops, and training sessions are required not only to introduce and explain the procedures but also to gather feedback and to improve the overall process. Additionally, future materials-testing and analytical research will enhance the basic framework developed for this project. Current project documents are initial editions to be revised and improved over the years.

In addition to the project team, a Project Review Panel has reviewed the damage evaluation and repair procedures and each of the three project documents. This group of experienced practitioners, researchers, regulators, and materials industry representatives reached a unanimous consensus that the products are technically sound and that they represent the state of knowledge on the evaluation and repair of earthquake-damaged concrete and masonry wall buildings. At the same time, all who contributed to this project acknowledge that the recommendations depart from traditional practices. Owners, design professionals, building officials, researchers, and all others with an interest in the performance of buildings during earthquakes are encouraged to review these documents and to contribute to their continued improvement and enhancement. Use of the documents should provide realistic assessments of the effects of damage and valuable insight into the behavior of structures during earthquakes. In the long run, they hopefully will contribute to sensible private and public policy regarding earthquake-damaged buildings.

Prologue
